

www.portwest.com/declarations







SATRA

CENTEXBEL

c	INCHES	CM	DE	FR
XS	26-28	68-72	42-44	34-36
S	30-32	76-80	46-48	38-40
M	33-34	84-88	50	42-44
L	36-38	92-96	52-54	46-48
XL	40-41	100-104	56	50-52
XXL	42-44	108-112	58-60	54-56
3XL	46-47	116-120	62	58-60
4XL	48-50	124-128	64-68	62-64

### TEST HOUSE

AGJENSIA E TESTIMIT, NAGOPATOPUR 3A USTINTBAHE. ISPITNA KUĆA, ZKUŠEBNÍ DŮM, TESTHUIS, TEST MA IA. TESTAA IA. ORGANISME NOTIFIE TESTIERHAUS AOMH AOKIMON TEST HOUSE I AROPATORIO TESTA VIETA TESTAVIMO ISTAIGA TECT KVRA TESTORGAN LABORATORIUM BADAJACE, CASA DE TESTE, UCIDITATEЛЬНЫЙ ЦЕНТР, ISPITNA KUĆA, CERTIFIKAČNÝ ORGAN, TESTNA HIŠA. LABORATORIO DE ENSAYOS, TESTHUS, TEST KURULUSU, ВИПРОБУВАЛЬНИЙ ЦЕНТЯ

INTERTEK The Warehouse, Brewery Lane, Leigh, WN7 2RJ UK

Notified body number: 0362

WEST West Yorkshire Joint Services, PO Box 5, YORKSHIRE Nepshaw Lane South, Morley, LS27 7JQ

Notified body number: 2019

Wyndham Way, Telford Way, Kettering, Northamptonshire,

NN16 8SD, United Kingdom

Notified body number: 0321

Bracetown Business Park, Clonee, Dublin 15, D15 YN2P Ireland

Notified Body: 2777

TNO TNO Certification BV. Laan Van Westenenk 501, 7334 DT.

Apeldoom, Netherlands,

Notified body number: 0336

Centexbel Technologie Park 7, B-9052, Zwijnaarde, Belgium Notified body number: 0493

BUREAU Tower Bridge Court, 224-226 Tower Bridge Road,

**VERITAS CPS** London, SE1 2TX England UK LTD

Notified body number: 0319

# PORTWEST | USER INFORMATION



Please read these instructions carefully before using this safety clothing. You should also consult your safety officer or immediate superior with regard to suitable garments for your specific work situation. Store these instructions carefully so that you can consult them at any time.



Refer to the product label for detailed information on the corresponding standards. Only standards and icons that appear on both the product and the user information below are applicable. All these products comply with the requirements of Regulation (FII 2016/425)

#### ISO 13688:2013 Protective Clothing (See Jahel)

General Requirements This European (A) Standard specifies general requirements for ergonomics, ageing, sizing, marking of protective clothing and for information supplied by the manufacturer.

A= Recommended height range of wearer B= Recommended chest girth of wearer

or removed.

C= Recommended waist girth of wearer

Tumble dry normal

D= Recommended inside leg measurement of wearer

Available Size & Selection: Fit according to correct chest and waist size, refer to size chart. These garments have built in allowance for comfort and to allow the garment to be worn over medium bulky clothing. To obtain overall protection, the wearer may need to wear gloves (to EN 407 or EN 12477), Boots (to EN 20345) and or Safety helmet (to EN 397). Storage: DO NOT store in places subject to direct or strong

sunlight. Store in clean, dry conditions. After-care: The manufacturer will not accept liability for garments where care labels have been ignored, defaced

thermal lining.

# EN 3/43 - 2003 ± A1-2007

Protection Against Rain (see label) Resistance to water penetration 3 levels

Y Resistance to water vapour penetration 3 levels

V Class 1 Minimum level

Class 2 Intermediate level

Class 3 Highest level of

Class 1 Minimum level Class 2 Intermediate level Class 3 Highest level

breath-ability Garments with removable sleeves only offer full protection when the sleeves are attached to the body of the garment. Recommended maximum continuous wearing time for a complete suit consisting of jacket and trousers without a

EN343: 2003		Duration of Wearing (in minutes)			
Temp:	Temp	Class 1	Class 2	Class 3	
Temperature of working environment	25°C 20°C 15°C 10°C 5°C	60 75 100 240	100 250 — —	200	

" " Means no limit for wearing time Water Vapour Permeability effect for coated fabrics or laminates in different ambient temperatures

Fibre Content Label: Refer to garment label for corresponding content details.

Warning: Where there is a hood, peripheral vision and hearing may be impaired.

Wash Care Labels - Refer to garment label for corresponding washing details

,,,										
30°	Max temp 30°C, mild process		Line dry	MAX	Maximum					
40°	Max temp 40°C, mild process	Ш	Drip line dry	50x	50 Washes					
40°	Max temp 40°C, normal process	$\bowtie$	Do not iron	MAX 25x	Maximum 25 Washes					
60°	Max temp 60°C, normal process	$\overline{a}$	Iron max 110°C	MAX	Maximum					
$\times$	Do Not Bleach	<u></u>	Iron max 150°C	<b>12</b> x	12 Washes					
Ø	Do not tumble dry	Ø	Do not dry clean	MAX	Maximum					
ō	Tumble druleus	P	Professional dry clean	<b>5</b> x	5 Washes					

## MANUFACTURER

PROFHUESI, ПРОИЗВОДИТЕЛ, PROIZVOĐAČ, VÝROBCE, TOOTJA, VALMISTAJA, FABRICANT, HERSTELLER, KATAZKEYAZTHZ, GYÁRTÓ, FABBRICANTE, RAŽOTĀJS, GAMINTOJAS, ПРОИЗВОДИТЕЛ, PRODUSENT, PRODUCENT, FABRICANTE, PRODUCATOR, ПРОИЗВОДИТЕЛЬ, PROIZVOĐAČ, VÝROBCA. PROIZVAIALEC, TILLVERKARE, ÜRETICI, BUPOGHUK

PORTWEST, Westport, Co Mayo, Ireland