

EN

Please read these instructions carefully before using this safety clothing. You should also consult your safety officer or immediate superior with regard to suitable garments for your specific work situation. Store these instructions carefully so that you can consult them at any time.

CE

Refer to the product label for detailed information on the corresponding standards. Only standards and icons that appear on both the product and the user information below are applicable. All these products comply with the requirements of Regulation (EU 2016/425).



ISO 13688-2013

Protective Clothing (see label)

General Requirements. This European Standard specifies general requirements for ergonomics, ageing, sizing, marking of protective clothing and for information supplied by the manufacturer.

A = Recommended height range of wearer

B = Recommended chest girth of wearer

C = Recommended waist girth of wearer

D = Recommended inside leg measurement of wearer



EN 1149 Protective Clothing with Electrostatic Properties

This Standard specifies electrostatic requirements for electrostatic dissipative protective clothing to avoid incendiary discharges.

This Standard is not applicable for protection against mains voltages.

EN 1149-3 : 2004 Charge decay test method for all fabrics.

EN 1149-5 : 2008 Performance

requirements for fabrics and garments.

EN 61349-5-1:2007 Garment meets requirement specified in Table 3 for point to point resistance.

Limitations of Use (EN 1149):

Garments must be worn with trousers or upper body garments also meeting the standards. There should be sufficient overlap between upper and lower garments to ensure no gaps in protection. Non conforming garments worn over the garment will eliminate effectiveness.

Always Wear Fastened:

- Workers wearing electrostatic dissipative protective clothing should be properly earthen. The resistance between the person and the earth shall be less than 10⁸, e.g. by wearing adequate footwear.
- The electrostatic dissipative protective clothing shall not be open or removed whilst in the presence of flammable or explosive atmosphere or whilst handling flammable or explosive substances.
- No modification of this garment e.g. adding logos is allowed after EC Type Approval. The electrostatic dissipative performance of the electrostatic dissipative protective clothing can be affected by wear and tear, laundering and possible contamination.
- The electrostatic dissipative protective clothing shall not be used in oxygen enriched atmospheres without prior of the responsible safety engineer.
- This garment is suitable for wear during an entire working day and contains no toxic substances that can be a real health adversary in any other way. No allergic reactions due to skin contact with this garment are known.
- Do not attempt to repair damaged garments.

Available Size & Selection:

Fit according to correct chest and waist size, refer to size chart. These garments have built in allowance for comfort and to allow the garment to be worn over medium bulky clothing. To obtain overall protection, the wearer may need to wear gloves (to EN 407 or EN 12477), Boots (to EN 20345) and or Safety helmet (to EN 397).

Storage:

DO NOT store in places subject to direct or strong sunlight. Store in clean, dry conditions.

After-care:

The manufacturer will not accept liability for garments where care labels have been ignored, defaced or removed.

Fire Content Label:

Refer to garment label for corresponding content details.

Warning:


Where there is a hood, peripheral vision and hearing may be impaired.

REF: 77U5P



EN 1149
CERTIFIED

	A		D	
	CM	CM	CM	CM
SHORT	152-164	74		
REG	164-176	79		
TALL	176-188	84		
X TALL	188-202	92		



B	INCHES	CM	EURO
XS	32"-34"	80-88	40-44
S	36"-38"	92-96	46-48
M	40"-41"	100-104	50-52
L	42"-44"	108-112	54-56
XL	46"-48"	116-124	58-62
XXL	50"-52"	128-132	64-66
3XL	54"-55"	136-140	68-70
4XL	56"-58"	144-148	72-74
5XL	60"-64"	152-160	76-80

C	INCHES	CM	DE	FR
XS	26-28	68-72	42-44	34-36
S	30-32	76-80	46-48	38-40
M	33-34	84-88	50	42-44
L	36-38	92-96	52-54	46-48
XL	40-41	100-104	56	50-52
XXL	42-44	108-112	58-60	54-56
3XL	46-47	116-120	62	58-60
4XL	48-50	124-128	64-68	62-64

MANUFACTURER

ПРОФІЕСІЯ, ПРОИЗВОДИТЕЛ, ПРОИЗВОДАЧ, УЇНОВСЄ, ТООТІЯ, ВІЛМІСТІЯ, ФАБРИКАНТ, НЕКСТЕЛЛЕР, КАТАЄКАУТІЗНІ, ГІЯРТО, ФАВВІКАНТЕ, РАЗОТІЯ, ГАМІНТОЛАС, ПРОИЗВОДИТЕЛ, ПРОДУСЕНТ, ПРОДУСЕНТ, ФАВВІКАНТЕ, ПРОДУКАТОР, ПРОИЗВОДИТЕЛЬ, ПРОИЗВОДАЧ, УЇНОВСЄ, ПРОИЗВОДІАЄЛ, ТІЛЛЕУКАРЕ, УРЕТІСІ, ВІРФОНІК

PORTWEST LIMITED, WESTPORT, CO MAYO, IRELAND

Download declaration of conformity @

www.portwest.com/declarations

TEST HOUSE









AGENCIJA E TESTIMIT, ЛАБОРАТОРИЈА ЗА ИЗПИТВАЊЕ, ИСПИТНА КУЌА, ЗКУЌЕБНИ ДЉМ, ТЕСТИШУ, ТЕСТ МАЈА, ТЕСТАЈА, ОРГАНСМЕ НЕСТИЕР, ТЕСТИЕРНАУС, АДМН АДКІМОН, ТЕСТ HOUSE, ЛАБОРАТОРИО, ТЕСТА ВІЕТА, ТЕСТАВІМО ІСТАІГА, ТЕСТ КУЌА, ТЕСТОРГАН, ЛАБОРАТОРИУМ БАДАЈАЄС, САСА ДЕ ТЕСТЕ, ІСПИТАТЕЛЬНИЙ ЦЕНТР, ІСПИТНА КУЌА, СЕРТИФІКАЦІЙ ОРГАН, ТЕСТНА НІЅА, ЛАБОРАТОРИО ДЕ ЕНСАУС, ТЕСТИШ, ТЕСТ КІРІУЛІУС, ВІРІУБОВАЛЬНИЙ ЦЕНТР

WEST YORKSHIRE JOINT SERVICES,

PO BOX 5, NEPSHAW LANE SOUTH, MORLEY, LS27 7JQ

NOTIFIED BODY NUMBER: 2019

Wash Care Labels : Refer to garment label for corresponding washing details.

-  Max temp 30°C, mild process
-  Max temp 40°C, mild process
-  Max temp 40°C, normal process
-  Max temp 60°C, normal process
-  Do Not Bleach
-  Do not tumble dry
-  Tumble dry low
-  Tumble dry normal

-  Line dry
-  Drip line dry
-  Do not iron
-  Iron max 110°C
-  Iron max 150°C
-  Do not dry clean
-  Professional dry clean

MAX	MAXIMUM 50	MAX	MAXIMUM 25	MAX	MAXIMUM 12	MAX	MAXIMUM 5
50x	WASHES	25x	WASHES	12x	WASHES	5x	WASHES

Download declaration of conformity @ www.portwest.com/declarations